

Creation of multiple tools (RSP2 and RSP3) (CAD)







© 2013 Renishaw plc. All rights reserved.

Renishaw® is a registered trademark of Renishaw plc.

This document may not be copied or reproduced in whole or in part, or transferred to any other media or language, by any means, without the prior written permission of Renishaw.

The publication of material within this document does not imply freedom from the patent rights of Renishaw plc.

Disclaimer

Considerable effort has been made to ensure that the contents of this document are free from inaccuracies and omissions. However, Renishaw makes no warranties with respect to the contents of this document and specifically disclaims any implied warranties. Renishaw reserves the right to make changes to this document and to the product described herein without obligation to notify any person of such changes.

Trademarks

All brand names and product names used in this document are trade names, service marks, trademarks, or registered trademarks of their respective owners.

Renishaw part no: H-1000-5325-01-A

Issued: 12 2013

Creation of multiple tools (RSP2 and RSP3) (CAD)

Care of equipment

Renishaw probes and associated systems are precision tools used for obtaining precise measurements and must therefore be treated with care.

Changes to Renishaw products

Renishaw reserves the right to improve, change or modify its hardware or software without incurring any obligations to make changes to Renishaw equipment previously sold.

Warranty

Renishaw plc warrants its equipment for a limited period (as set out in our Standard Terms and Conditions of Sale) provided that it is installed exactly as defined in associated Renishaw documentation.

Prior consent must be obtained from Renishaw if non-Renishaw equipment (e.g. interfaces and/or cabling) is to be used or substituted. Failure to comply with this will invalidate the Renishaw warranty.

Claims under warranty must be made from authorised service centres only, which may be advised by the supplier or distributor.

Trademarks

Windows 98, Windows XP, Windows 2000 and Windows NT are registered tradenames of the Microsoft Corporation.

IBM is the tradename of the International Business Machines Inc

All trademarks and tradenames are acknowledged.

Contents

1	Creation of multiple tools (RSP2 and RSP3) (CAD)		6
	1.1	Tutorial pre-requisites	6
	1.2	Tutorial objectives	6
2	Introduction		7
3	Build	an RSP2 probe and stylus assembly	8

1 Creation of multiple tools (RSP2 and RSP3) (CAD)

1.1 Tutorial pre-requisites

• Student must have completed the 'Creating a new environment, tools and calibration of tools' tutorial


1.2 Tutorial objectives


- Further exposure to Renishaw specific hardware and software interaction
- Further exposure to the concept of multiple tool systems and hardware definition
- Consideration of hardware / software interaction


2 Introduction


This tutorial will provide the student with further information on the creation of multiple REVO specific tools. These methods comply with the I++ standard of CMM interface. UCCserver and this tutorial is for use with any Renishaw or OEM client software.


3 Build an RSP2 probe and stylus assembly






















NOTE: This message is only issued once during the creation of the first tool of a new environment.


RefTool: This tool records the location of the sphere when calibrated. It cannot be indexed and should not be used for general measurement functions.







Build another RSP2 stylus assembly:










NOTE: This will NOT delete any tools.




















There are now two RSP2 tools:




Build an RSP3 probe and stylus assembly:
































Build another RSP3 stylus assembly:









All tools must be calibrated before use.

The RSP2 uses inferred calibration for any angular position.

The RSP3-n must be calibrated at each angular position.

Renishaw plc

New Mills, Wotton-under-Edge, Gloucestershire, GL12 8JR United Kingdom T +44 (0)1453 524524 F +44 (0)1453 524901 E uk@renishaw.com www.renishaw.com



For worldwide contact details, please visit our main web site at www.renishaw.com/contact



H-1000-5325-01